


P29332  
Sloaner

~~Large window~~

1 OF 1.

~~2 of 2~~

Window Along This Wall



BATH - BIG TILES - NO VISIBLE CRACKS

(TIGHT DOOR)

KITCHEN

TILES - CRACKS, DIRT,

(Approx 20mm)

+ DEBRIS (Some GROUT MISSING)

(TIGHT DOOR)

RAISED HEARTH

(Approx 30mm)

HOONBOARDS NOT GROUT IN THIS ROOM