

Job No: P29433  
Name: OGTEN  
Address: 3 MILTON MANOR  
Clarendon Club (cont)  
Tel: W14 9RP  
Sheet: 1 OF 1

XANADU XAN-903

BILLY 3-2-20 2ND CAM



BUM TO EXISTING WOOD TRIM + 12MM SHIM REQUIRED

WOOD FRAMBANDS

W/ 1/2" LOCK LINE ON FEET

REQUIRES AN NEW GRILLER + 12MM SHIM

CURTAIN TRACKS - CURTAIN AREA + SICK GRILLER

FURNITURE - FRODO