



Job No: P29750
 Name: ELLIS
 Address:
 Tel:
 Sheet: 10FI
HAVANA - HAV-21
 = 250 x 400
 = 10M²

FRONT Bedroom (Remedial)



* Patch repair using uplited CARPET from Small back Bed + New felt + tile
 * to replace water Damaged sections

BACK Bed (Remedial)



* Also, Re-pin under nose of 2nd B/nose on 1st flight STAIRS (filled previously)

Customer to pay CASH direct to fitter for remedial work