


P30021
~~Falstead~~
 Verschoyle Interiors Ltd
 1 of 2

Wool Cord
 Col. olive (5787)
 Cut Plan ① 310 x 500
 Cut Plan ② 315 x 500
 625 x 500
 = 31.25m²

v/Lay:-
 Smaller bed = 10.50m²
 Larger Bed = 13.00m²
23.50m²

Remedial Work



P30021

~~Forrestel~~


Verschoyle Harrison & Co

20F2

use uplfted CARPET from Daughter's Bed to replace this Damaged Section (UPLFT BY BUILDERS - LEFT ON SITE)

1st floor

Re-stretch on width at wood T/Hold + to left of T/H. See photo



~~Remedial Work (Quote Sep)~~


~~Replace other ALI BALK on 157 floor landing to SATIN ALI~~

~~T/E x 1 (12mm tile)~~

~~D/N x 3~~

~~B/Ware 50x89 A/C wool put stripe~~

*Quote to replace CAT Damaged?? step



Seam Here

BAD Mott Damage (Gave ASA's tentlet)