


151 Rock front Bedroom

Job No: R19293
 Name: HARLSON
 Address: 46 TOLVENE RD
 SWL081A
 Tel:
 Sheet: 1 of 1



FLOORBOARD BROKEN
 ADVISED CUSTOMER TO GET FIXED!

WOOD FROM - NO VLIKT
 NEW SLEECE REQ'D 1/OUT
 EXISTING SATIN DIN AP
 TO REMAIN


FRONT BEDROOM

TALANTO II
 COLOUR TAR-10
275 x 400 (11M²)

CUSTOMER ADVISED TO HAVE DRAWERS BENEATH BED
 TAKEN OUT / MOVED IN TO INSTALLATION!

REAR BEDROOMS
225 x 400 (9M²)

TALANTO II COLOUR TAR-10



WOOD FROM
 VLIKT TRIM ON RUBBER
 MAKE WIRES!! TO INSIDE OF CRIPPER
 FURNITURE FGIS