

WARRANTY CALL

Job No: 526713
Name: MR E. COLES
Address: 4 MARTINDALE
E SHEEN
SW14 7AL
Tel: _____
Sheet: _____ of: _____


①

1st Floor R Bed

Cpt coming out of Drape
Starting to fray.

②

TLC L shaped, not
happy with the V



I explained that it was necessary, but it needs to
be tidied up.

③ Bottom Star Customer thinks it is too baggy. (Riser)

I told him that it was OK.

But try to tighten it a bit