


1



Job No: 526866

Name: GOODWIN

Address:

Tel:

Sheet: of:

ORIGINAL PIECES FROM ABOVE PLAN THAT WERE LEFT ON SITE PREVIOUSLY WERE DAMAGED BY BUILDERS.

Plan 1) 1.50 x 5m

7.5m²

PHASE 2