

Warranty call

3 areas to sort

(1) Bottom step on top flight
allow rucking up

(2) 1st land

Between Bath + we gripper spike to hammer down

(3) Approx 9" out from we, get bubbles, needs
stretching

(1001)

mrcarpets
S27173

Job No: Mrs SINNOTT

Name: 18 Leinster Ave

Address: E Shes

Tel: SW14 7JP

Sheet: of:

Alan

Tues 2/6/15

Late AM / PM