

# WARRANT CALL

2 Bathrooms

Tiles coming unstuck in various places.

Replace tile behind wc where  
badly cut around pipes

Customer not happy with sealant around  
perimeter. Need to re-do in places

When finished, walk the job with the  
customer + leave her satisfied that all  
OK

(1 of 1)

Kewin Glad  
Tue 21/7/15  
all day

S27206

Mr L. HAWETT  
32 Ellerton Road  
Wandsworth  
Tel: SW18 3NN  
Sheet of: