


CS 30073  
DABR, INFO NOTES

WHOLE WINE CANT  
WINE CHASE  
HERE



BE CHASED  
CUSTOMER AWARE

EXISTING GRIPPER  
UPHST + DISPOSAL WORK  
NEW U/LAY  
WOODEN SUBFLOOR  
NO BAR WORK

CUST TO DISASSEMBLE  
SHELVING UNIT + HAVE  
RE-FITTED AFTER CRT  
FITTING

2 x FLIGHTS OF  
COMMUNAL STAIRS,

NET  
MEASURES

CRT ISSUED  
3-12 x 4.25

CUSTOMER ASKED ME IF WE  
WOULD DISASSEMBLE SHELVING, I SAID NO!!

CUSTOMER ASKED ME IF WE WOULD  
RE-ASSEMBLE BED FRAME AFTER FITTING  
I SAID NO!!

WE ARE NOT HANDY MEN,  
BUT CRT FITTERS