

Restretching details

P. ...

S 30804

Mrs S. Marshall
116 Palewell Park
Address: Suite 834

1st floor rear bed

Bulge by door, might be subfloor
+ utility problem

1st floor Front bed

Whole room needs stretching

Top Front bed (near) whole room needs stretching

Top land Needs restretch

Top Rear bedroom needs restretch



2/8/21
SLOT 1-2

(TOP)