



Job No:

Name:

Smith


Address:

S/35933

Tel:

Sheet:

1 of 1
1 of 1




Caulking required or
Sealant to stop
✓ dust at
skitts.

Also Paperfelt
a MUST

Uplift a separate
visit.

Furniture

Mitb edge
corner



WESTEND
PRESTIGE
— ENMINA
330 x 657